



Technical News

Sony Imaging Products & Solutions Inc. © 2019

Ref. No.	Issuer company	Issue (yyyy/mm/dd)	Last modification (yyyy/mm/dd)
PV19DSC506	Digital Imaging Group	2019/09/17	
Subject			
Repair services to replace LCD panels			
Model (System model)	Destination	Serial number	Color
DSC-W830	All	ALL	All

SYMPTOM

When replacing the LCD module or main board, check the combination and take necessary measures.
(Details)

*The current LCD module is no longer available. Replacement parts will be used for repair.

*Identify the type of LCD module from the flex print.

SOLUTION

Refer to Table 1 below for how to identify LCD modules.





	Product replaced with GiantPlus (GP)	CPT Current product
Product name	GPM1118B0-A	CLAA027GF22DG
Parts No.	1-004-018-11	1-811-263-3*
FPC (Terminal surface)	 <div style="border: 1px solid black; padding: 5px; display: inline-block;">Printed as "GIANTPLUS"</div>	 <div style="border: 1px solid black; padding: 5px; display: inline-block;">Printed as "CLAA027GF22DG"</div>
FPC	 <div style="border: 1px solid black; padding: 5px; display: inline-block;">Printed as "GPM1118B0-A"</div>	 <div style="border: 1px solid black; padding: 5px; display: inline-block;">Printed as "M1118B0"</div>

Table 1. How to identify an LCD module

Conditions of Use:

- (1) Only Sony Group employees are permitted to access and use this information. To disclose or disseminate to any other parties is forbidden.
- (2) Destroy or erase any and all portion of this information promptly in an irrecoverable and secure fashion, after achieving the purpose of use of this information.
- (3) Do not copy, replicate, reproduce, alter, translate, transmit, sell, lease, or distribute this information in whole or in part without the prior written permission of the author.
(Notwithstanding foregoing, it is permitted to copy and distribute this information to the Sony Group employees whose duties a need-to-know.)
- (4) Please notify immediately any leakage, loss, theft, misappropriation, or other misuse of this information by e-mail to the following address:
somk-gcs-tissnexim-adm@jp.sony.com

Revision of Information:

This information may be changed or updated at any time without any prior notice. Please confirm that this information is up-to-date before using it.

Refer to the repair flow below.

Note 1: Main circuit board (Flat/GP A-5014-382-A (SY-1035 COMPL_GP)) is marked

Marking: Blue point ●

